

Jaguar I-PACE eTROPHY Championship Bulletin

Bulletin Number
MSA Permit Number

CB015
RCINT/004

FROM: Series Coordinator
TO: All Drivers
CC: Race Officials

DATE: 02/5/2019
TIME: 18:00

Additions/Changes to Championship Regulations

5.6.4 Aerodynamic devices

The original position of the wing section is allowed to be adjusted within the range specified (5 options). Taping over of any slots in the bodywork, wings or other permanent parts, joints and openings is not allowed, except when bodywork parts are at risk of falling off due to damage. The taping over these damaged parts is only allowed during the session in which the damage occurs, having to be fixed for the following session. Any changes made outside the above set parameters will render the Car noncompliant with the Technical Regulations and may be subject to penalties from the race Stewards.



Marion Barnaby
Jaguar I-PACE eTROPHY Championship Manager



OFFICIAL PARTNERS



OFFICIAL SUPPLIERS